

Model Name	Original FW Version	Updated FW Version	Minimum BIOS Ver	Update Type	Update Tool ¹
LIFEBOOK E544 LIFEBOOK E554	FW4.32	FW4.34	No Dependency	FW Update Utility	FPC48-2383-01 Infineon TPM1.2 Firmware Update V4.34
LIFEBOOK E546 LIFEBOOK E556	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0
LIFEBOOK E546 LIFEBOOK E556	FW5.51	FW5.62	vPro V1.18 non-vPro V1.25	BIOS update and FW Tool ²	FPC48-2381- 01_Infineon_TPM2.0_ Firmware_Update_Tool_V1.0.0
LIFEBOOK E547 LIFEBOOK E557	FW5.61	FW5.62	vPro V1.13 non-vPro V1.09	BIOS update and FW Tool ²	FPC48-2381- 01_Infineon_TPM2.0_ Firmware_Update_Tool_V1.0.0
LIFEBOOK E734 LIFEBOOK E744 LIFEBOOK E754	FW4.32	FW4.34	No Dependency	FW Update Utility	FPC48-2383-01 Infineon TPM1.2 Firmware Update V4.34
LIFEBOOK E736 LIFEBOOK E746 LIFEBOOK E756	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0
LIFEBOOK E736 LIFEBOOK E746 LIFEBOOK E756	FW5.51	FW5.62	vPro V1.21 non-vPro V1.27	BIOS update and FW Tool ²	FPC48-2381- 01_Infineon_TPM2.0_ Firmware_Update_Tool_V1.0.0
LIFEBOOK P727	FW5.61	FW5.62	V1.12	BIOS update and FW Tool ²	FPC48-2381- 01_Infineon_TPM2.0_ Firmware_Update_Tool_V1.0.0
LIFEBOOK T725	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0
LIFEBOOK T726	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0
LIFEBOOK T726	FW5.51	FW5.62	V1.15	BIOS update and FW Tool ²	FPC48-2381-01 Infineon TPM2.0 Firmware Update Tool V1.0.0
LIFEBOOK T734	FW4.32	FW4.34	No Dependency	FW Update Utility	FPC48-2383-01 Infineon TPM1.2 Firmware Update V4.34
LIFEBOOK T904	FW4.32	FW4.34	No Dependency	FW Update Utility	FPC48-2383-01 Infineon TPM1.2 Firmware Update V4.34
LIFEBOOK T935	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0
LIFEBOOK T936	FW5.51	FW5.62	V1.14	BIOS update and FW Tool ²	FPC48-2381- 01_Infineon_TPM2.0_ Firmware_Update_Tool_V1.0.0
LIFEBOOK T936	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0
LIFEBOOK T937	FW5.61	FW5.62	V1.13	BIOS update and FW Tool ²	FPC48-2381-01 Infineon TPM2.0 Firmware Update Tool V1.0.0
LIFEBOOK U727	FW5.61	FW5.62	V1.18	BIOS update and FW Tool ²	FPC48-2381-01 Infineon TPM2.0 Firmware Update Tool V1.0.0
LIFEBOOK U727 6th Gen	FW5.61	FW5.62	V1.06	BIOS update and FW Tool ²	FPC48-2381- 01_Infineon_TPM2.0_ Firmware_Update_Tool_V1.0.0
LIFEBOOK U745	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0

Model Name	Original FW Version	Updated FW Version	Minimum BIOS Ver	Update Type	Update Tool ¹
LIFEBOOK U745	FW5.51	FW5.62	V1.20	BIOS update and FW Tool ²	FPC48-2381-01_Infineon_TPM2.0_Firmware_Update_Tool_V1.0.0
LIFEBOOK U747 LIFEBOOK U757	FW5.61	FW5.62	V1.18	BIOS update and FW Tool ²	FPC48-2381-01_Infineon_TPM2.0_Firmware_Update_Tool_V1.0.0
LIFEBOOK U747 6th Gen LIFEBOOK U757 6th Gen	FW5.61	FW5.62	V1.06	BIOS update and FW Tool ²	FPC48-2381-01_Infineon_TPM2.0_Firmware_Update_Tool_V1.0.0
LIFEBOOK U904	FW4.32	FW4.34	No Dependency	FW Update Utility	FPC48-2383-01 Infineon TPM1.2 Firmware Update V4.34
LIFEBOOK U937	FW5.61	FW5.62	V1.10	BIOS update and FW Tool ²	FPC48-2381-01_Infineon_TPM2.0_Firmware_Update_Tool_V1.0.0
STYLISTIC Q616	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0
STYLISTIC Q616	FW5.51	FW5.62	V1.12	BIOS update and FW Tool ²	FPC48-2381-01_Infineon_TPM2.0_Firmware_Update_Tool_V1.0.0
STYLISTIC Q665	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0
STYLISTIC Q704	FW4.32	FW4.34	No Dependency	FW Update Utility	FPC48-2383-01 Infineon TPM1.2 Firmware Update V4.34
STYLISTIC Q736	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0
STYLISTIC Q736	FW5.51	FW5.62	V1.15	BIOS update and FW Tool ²	FPC48-2381-01_Infineon_TPM2.0_Firmware_Update_Tool_V1.0.0
STYLISTIC Q737	FW5.61	FW5.62	V1.11	BIOS update and FW Tool ²	FPC48-2381-01_Infineon_TPM2.0_Firmware_Update_Tool_V1.0.0
STYLISTIC Q775	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0
STYLISTIC R726	FW4.40	FW4.43	No Dependency	FW Update Utility	FPC48-2382-01 Infineon TPM1.2 Firmware Update V4.43.257.0
STYLISTIC R726	FW5.61	FW5.62	vPro V1.18 non-vPro V1.18	BIOS update and FW Tool ²	FPC48-2381-01_Infineon_TPM2.0_Firmware_Update_Tool_V1.0.0

1. Please see FAI Mobile Downloads site for postings.

2. The FW Tool must be used with BIOS update, although the BIOS update can be applied separately.

WARNING:

Clearing the TPM resets it to factory defaults. All created keys will be deleted and you will therefore lose access to any data encrypted by those keys. For more detailed information regarding TPM Clear please refer also to the following [Microsoft site](#).

* Please note that this information is subject to change without any prior notice.