

Soil and Groundwater

Business sites where soil or groundwater contamination has been found

Site Name	Location	Cleanup and Countermeasure status	Monitoring Well Maximum Value (mg/L)		Regulated Level (mg/L)
			Substance	Measured Value	
Fujitsu Technology Park (former Kawasaki Plant)	Kawasaki City, Kanagawa Prefecture	We are continuing to clean up VOCs by pumping and aeration.	1, 2-dichloroethylene	1.5	0.04
			Chloroethylene	5.7	0.002
Oyama Plant	Oyama City, Tochigi Prefecture	We are continuing to clean up VOCs by pumping and aeration.	Trichloroethylene	0.3	0.01
			1, 1-dichloroethylene	0.25	0.1
			1, 2-dichloroethylene	4.806	0.04
			Chloroethylene	1.177	0.002

- [Response to Environmental Risks](#)